

UC Irvine

Facilities Management

EXHAUST FAN REPLACEMENT / OUTAGE

Location: Engineering Tower, Room #142
Building #303

Disruption/Outage: Exhaust Fan Outage, Increased Construction Noise, Dust and Traffic.

Date: Friday May 29, 2026 through Tuesday, June 2, 2026

Duration: Scheduled to begin on 5/29 at 8:00AM, lasting approximately 5 days, ending on 6/2 at approximately 3:00PM.

Details: Exhaust fan #142 is scheduled to be replaced with a new exhaust fan. Crane will be on site on Saturday, May 30 to lift new exhaust fan on top of ICS roof and bring down the old exhaust unit. Contractors will be working on the roof top during this time frame.

* We use South Coast Air Quality Management District (SCAQMD) compliant low-VOC materials (e.g., paints, sealants, etc.). For any health concerns, please contact Environmental Health & Safety at x4-6200

We appreciate your cooperation and apologize for any inconvenience this may cause. If you have any questions or concerns, please contact David Hooks at 949-422-0539 or Dhooks@uci.edu

Cc: Building Facility Manager (please route to appropriate MSO/affected faculty and/or staff)

DATE POSTED: May 12, 2026
PLEASE POST UNTIL: June 5, 2026